Tool and Equipment

April 2023

Prepared by Transportation Planning Missouri Department of Transportation

Rear Rock Guard



Description and Benefit

When mowing the right of way, foreign objects can sometimes hit the back glass causing it to break. The glass then ends up in the cab with the operator. This is a safety issue for the operator as well as an expense to MoDOT and down time till we can get another glass. The old rock guard was mounted to the lift arms and did not always cover the rear glass while going up and down slopes. With this style it is always protected and only has one mounting point instead of two.

For More Information Contact

Southeast District/Maintenance Daniel Stanfill at <u>Daniel.Stanfill@modot.mo.gov</u> or 573-225-2319.

Southeast District/Maintenance Brad Cook at <u>Brad.Cook@modot.mo.gov</u> or 573-561-6321.

